ZERO₂

Designed by:
Brioschi Tommaso
Lanzoni Lorenzo
Fidone Gianluca

Index

A_ Initialization

B_ Cuff application

C_ Read / output phase

D_ Battery low

E_ Recharge

!_ Warnings

ZERO₂

A_ Push the start button

B_ Enter O2 in the appropriate cuff

C_ Read / output phase

Stable oxygen
Value 95.5 % (±2)

Deficiency of oxygen
Value < 93.5 %

D_ Battery low

Excess of oxygen
Value > 97.5 %

Low battery it will
switch off soon

E_ Recharge through cable USB micro